



## 2. Emergency operation of Water Supply Systems in 0206 Earthquake

### 2.1 Emergency Water Supply Stations (Vehicle Transportation)

#### 1. Emergency Water Supply Station (Water Supply Point):

There are 142 Emergency Water Supply Station, generally one of these stations located within a 2km radius of consumer's home . Consumer can check the location of nearest Emergency Water Supply Station (Water Supply Point) from Public Notice or website of TWC and Tainan City Government.

#### 2. Tour water supply: TWC uses water trucks to transport water to Emergency Water Supply Station (Water Supply Point). In accordance with the 22 vehicle route/stop for solid waste collection truck to send water tankers for providing patrol service.

#### 3. Water tanker or Fire-fighting truck injected water into pipeline for supplying water to consumer's water tank.

### 2.2 Emergency Water Supply Operation

#### 1. Due to the earthquake, Tainan Water Supply System had been seriously damaged, it needed time to restore water supply system gradually after repairing damaged water infrastructure , especially the damaged 2,000mm(in diameter) transmission line which was located under the collapsed 17-story Weiguan Jinlong Building ( see Fig.2). TWC used backup 1,750 mm transmission line to transfer water and laying 1,350 mm emergency temporary transmission pipe on the ground ( see Fig.3 and Fig.5) by reducing pressure to supply water. Owing that the total volume of water is insufficient and water pressure is low, the consumers living in highland region and dead end areas are still suffering water shortage problem.

#### 2. Highland region : By operating the valves during night time to supply water .

#### 3. Dead end areas : By using Water tanker or Fire-fighting truck injected water into pipeline for supplying water to consumer's water tank( see Fig.4).



Fig.2 The collapsed 17-story Weiguan Jinlong residential building



Fig.3 1,350 mm emergency temporary transmission pipe on the ground



Fig.4 Water tanker injected water into pipeline for supplying water to consumer's water tank

### 2.3. Repairing Pipelines

1. After inspection, there were about 7,948 cases of reporting water interruption, and about 4,710 leaky pipes (72 cases are larger than 300mm in diameter). The repairing teams cooperated with outsourcing contractors were dispatched immediately to fix leaky pipes.
2. Yongda Road damaged 2,000mm (in diameter) pipe:  
After the Tainan City Government has cleaned up the collapsed Weiguan Jinlong Building, Repairing teams of TWC rushed to repair the pipe and completed at 24:00 on February 24th then restore water supply.
3. Xinhua Zhongxiao Road damaged 2,000mm (in diameter) pipe :  
The damaged pipe was constructed by pipe jacking method and was under 8 meters from the ground, total length of 1,200 meters. After inspection it was found there were 7 cracks in the pipe. It was repaired at 00 : 30 on February 24th.  
Location of damaged 2,000mm pipe and



Fig.5 Location of damaged 2,000mm pipe and 1,350 mm temporary pipe

## 2.4 Communicating with the Public during the earthquake

Effective communication with employees, customers, and reporters is a key element of emergency response. When the crisis hits, our communication measures are following:

- Daily regular press releases are available on TWC website for information on water and water supply stations.
- Provide free Mobile Water Housekeeper APP for query service (see Fig.6).
- Established FB to provide user for consultation platform.
- Toll-free hotline at 1910.



Fig.6 Mobile Water Housekeeper APP

### **3. Lessons Learned from the 0206 earthquake**

#### **3.1 Establishing Forward Command Post:**

Forward Command Posts shall be established on the spot of serious disaster areas. The post shall be headed by President of Taiwan Water Corporation and operated by TWC HQ to integrate TWC's all kind of resource to relief the disaster as soon as possible.

#### **3.2 Water service message:**

- Establish Line or Messages Group for government officials, elected representatives to inform emergency message at the first time.
- Set up the news media center to provide complete, accurate, and timely information.
- Tell the truth and express empathy.
- Acknowledge uncertainty and offer to get back with more information later.

#### **3.3 Continuously strengthen the supply system and take aseismic measures.**

#### **3.4 Improve the restoration time needed for highland region and dead end areas.**

### **4. What To Do Next**

- Constructing Nan-hua dual transmission line system
- Improving plans for water supply in Highland region
- Developing smart water networks across the system
- Surveying seismic and geologic hazards across the system
- Replacing aging pipe remains a big source for work
- Seismic vulnerability and condition assessment for large diameter pipeline
- Capacity building and institutional strengthening for water loss control
- Enhance training for emergency management capacity

### **5. Conclusion**

- Location on the seismic area that we cannot predict, but we can do our best to strengthen the water system and do well prepared to face the coming hazards.
- In response to the challenges, we need to improve the old facilities, establish supporting and backup system.
- Different environments face different disasters, we suggest focusing on the most critical threats and engaging in the proper solutions.

### **REFERENCES**

- [1] Global Earthquake Epicenters (6 February 2016). "Map of the earthquake M6.4 – 28km NE of Pingtung, Taiwan".
- [2] "Powerful earthquake rocks southern Taiwan". [www.aljazeera.com](http://www.aljazeera.com). Retrieved 4 April 2016.
- [3] United States Geological Survey, "M6.4 – 28km NE of Pingtung, Taiwan". 5 February 2016. Retrieved 5 February 2016.
- [4] "Taiwan earthquake: Rescuers in frantic search for missing". *BBC News*. Retrieved 5 February 2016.
- [5] "68 aftershocks recorded after major earthquake". Focus Taiwan. 8 February 2016. Retrieved 18 July 2016